PS/2 Connector
Used for Keyboard and Mouse
On Most PCs.

6   5   Clock

+5 VDC   4   3   Ground/Common

2   1   Data

FEMALE Jack

Looking at holes in <u>jack</u> from outside of computer
(Soldering end of mating plug)

Stephen H. Smith   WA8LMF@aol.com   20 Oct 2001